





<b>Tunnel Mill Polymer, Inc.</b>	Action	By	Date
	Drawn	SD	5/8/02
	Checked	SD	5/8/02
	Revised		
Calix ODC 5/10 on B547806-00 / U487248 Planview	Revised		
	Revised		
	Revised		
	Drawing Number		Revision
DBDACA		A	
			
The aluminum access panel, with safety tread plate, covers an opening as shown.			
<a href="#">View a .dwg file</a>		<a href="#">Return to Catalog</a>	





<b>Tunnel Mill Polymer, Inc.</b>	Action	By	Date
	Drawn	SD	5/8/02
	Checked	SD	5/8/02
	Revised		
Calix ODC 5 /10 on B547806-00 / U487248 Elevations	Revised		
	Revised		
	Revised		
	Revised		
Drawing Number		Revision	
DBDACA		A	
The aluminum access panel, with safety tread plate, covers an opening as shown.			
<a href="#">View a .dwg file</a>		<a href="#">Return to Catalog</a>	

<b>Tunnel Mill Polymer, Inc.</b>	Action	By	Date
	Drawn	SD	5/8/02
	Checked	SD	5/8/02
	Revised		
Calix ODC 5/10 on B547806-00 U487248 Elevations	Revised		
	Revised		
	Revised		
	Revised		
Drawing Number		Revision	
DBDACA		A	
The aluminum access panel, with safety tread plate, covers an opening as shown.			
<a href="#">View a .dwg file</a>		<a href="#">Return to Catalog</a>	

