




Tunnel Mill Polymer, Inc.	Action	By	Date
	Drawn	SD	5/8/02
	Checked	SD	5/8/02
	Revised		
Calix ODC 20 @ 90 on B547806-12 / U487248 Elevations and Planview	Revised		
	Revised		
	Revised		
	Drawing Number		Revision
	DBDECA		A
<p>The aluminum access panel, with safety tread plate, covers an opening as shown.</p>			
View a .dwg file		Return to Catalog	





Tunnel Mill Polymer, Inc.	Action	By	Date
	Drawn	SD	5/8/02
	Checked	SD	5/8/02
	Revised		
Calix ODC 20 @90 on B547806-12 / U487248 Elevations and Planview	Revised		
	Revised		
	Revised		
	Revised		
Drawing Number		Revision	
DBDECA		A	
The aluminum access panel, with safety tread plate, covers an opening as shown.			
View a .dwg file		Return to Catalog	



Tunnel Mill Polymer, Inc.	Action	By	Date
	Drawn	SD	5/8/02
	Checked	SD	5/8/02
	Revised		
Calix ODC 20 @ 90 on B547806-12/ U487248 Elevations and Planview	Revised		
	Revised		
	Revised		
	Drawing Number	Revision	
	DBDECA	A	
	16"	32"	14 1/2"
		29"	
The aluminum access panel, with safety tread plate, covers an opening as shown.			
View a .dwg file		Return to Catalog	