






Tunnel Mill Polymer, Inc.	Action	By	Date
	Drawn	bD	8/5/03
	Checked	SD	8/5/03
	Revised		
Occam rtc 4110 on B547806-12 / U487248 Elevations and Planview	Revised		
	Revised		
	Revised		
	Drawing Number	Revision	
		A	
			
<p>The aluminum access panel, with safety tread plate, covers an opening as shown.</p>			





Tunnel Mill Polymer, Inc.	Action	By	Date
	Drawn	BD	8/5/03
	Checked	SD	8/5/03
	Revised		
Occam rtc 4110 on B547806-12 / U487248 Elevations and Planview	Revised		
	Revised		
	Revised		
	Drawing Number		Revision
		A	
<p>16" 32"</p>		<p>14 1/2" 29"</p>	
The aluminum access panel, with safety tread plate, covers an opening as shown.			
View a .dwg file		Return to Catalog	



Tunnel Mill Polymer, Inc.	Action	By	Date
	Drawn	BD	8/5/03
	Checked	SD	8/5/03
	Revised		
Occam rtc 4110 on B547806-12/ U487248 Elevations and Planview	Revised		
	Revised		
	Revised		
	Revised		
Drawing Number		Revision	
		A	
<p>16"</p> <p>32"</p>		<p>14 1/2"</p> <p>29"</p>	
The aluminum access panel, with safety tread plate, covers an opening as shown.			
View a .dwg file		Return to Catalog	